

From: Aja Chase <aja.chase@ericsson.com>
Sent: Friday, April 5, 2024 1:30 PM
To: CSC-DL Siting Council <Siting.Council@ct.gov>
Subject: EM-ATT-076-231207

Good Afternoon CSC,

Please find a photo of overall work completed at this site, as construction is now complete. If you need any additional information, please let us know!

Thanks,

Aja Chase
Construction Manager
ATT New England
401-952-6205

Mar 27, 2024 at 9:59:56 AM
17 Cottage Rd
Madison CT 06443
United States





Final Report of Special Inspections

Date: March 28, 2024

Project: AT&T Wireless (5G/CBAND/RF Mod/BBU)
Site Id: CTL032517
FA Number: 10546793
Location: 17 Cottage Road, Madison, CT
Owner: AT&T Wireless

Engineer of Record: Derek Creaser, P.E.
Centerline Engineering Svcs., PA

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved.

Representatives of Centerline Engineering Svcs., PA performed the Final Inspections after the construction of the telecommunications facility at the above-referenced address. The Final Inspection was performed on March 21, 2024.

Based on my knowledge, information, and belief the AT&T Installation substantially conforms to the approved plans, IBC 2018, 2022 CT State Building Code, Structural Standards for Antenna Supporting Structures and Antennas (ANSI/TIA-222-H), and the following:

Final Construction Drawings dated 10/20/23, prepared by Centerline Engineering.
Structural Analysis dated 01/30/23, prepared by P. Marshall & Assoc.

All deviations from the approved plans do not endanger the intended occupancy of the facility and equipment substitutions are approved as equivalent to the original specifications.

This report does not include inspections for the findings of the global stability analysis and modifications to the structure. Those modification inspections, if required, are strictly the responsibility of the tower owner & general contractor performing such design and installation. Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Special Inspector

Derek Creaser, P.E.
Director of A&E
Centerline Engineering Svcs., PA
dcreaser@clinellc.com

Centerline Engineering Services, PA
750 W Center St, Suite 301
West Bridgewater, MA 02379
781-713-4725